PATENT Cole

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)		
MAKOTO SATOH ET AL.		:	Examiner: Jason Whipkey	
		:	Art Unit: 2612	
Appln. No.: 09/110,018)		
Filed: July 2, 1998)		Certificate
For:	IMAGE PICKUP APPARATUS, METHOD, AND STORAGE MEDIUM)		OCT 0 3 2006
	FOR DISPLAYING, COMPRESSING, AND ENCODING IMAGE DATA	·)		of Correction
	THE LIVE OF THE STATE OF THE ST	·)		
U.S. Patent No.: 7,038,724 B2)		
Issued:	May 2, 2006	;	September 28, 2006	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

10/02/2006 SDENBOB1 00000022 7038724 01 FC:1811 100.00 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 594423v1

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, insert --5,043,816 8/1991 Nakano et al. 348/333.01--.

COLUMN 1:

Line 29, "requiring the" should read --requiring of the--.

COLUMN 2:

Line 42, "output;" should read --output--.

COLUMN 3:

Line 29, "a (CD1" should read --a CCD1--.

COLUMN 5:

Line 57, "frames." should read --frame.--.

COLUMN 6:

Line 13, "facilitate" should read --facilitates--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>US 7,038,724 B2</u>

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 9, "memory 13C" should read --memory 130--;

Line 10, "such." should read --such--;

Line 53, "106 in" should read -- 106 is in--; and

Line 56, "time" should read --time:--.

COLUMN 10:

Line 1, "components" should read --component--.

COLUMN 11:

Line 62, "second resolution" should read --second-resolution--.

COLUMN 12:

Line 4, "first-and" should read --first- and--;

Line 15, "a" should read --an--;

Line 37, "second resolution" should read --second-resolution--; and

Line 52, "first-and" should read --first- and--.

COLUMN 13:

Line 10, "wits" should read --puts--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,038,724 B2</u>

No. of add'l. copies @ 30¢ per page

90% - 3 2000



PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 6, "second" should read --second---.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

- 3 2000

No. of add'l. copies @ 30¢ per page



PATENT NO. <u>US 7,038,724 B2</u>

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, insert --5,043,816 8/1991 Nakano et al. 348/333.01--.

COLUMN 1:

Line 29, "requiring the" should read --requiring of the--.

COLUMN 2:

Line 42, "output;" should read --output--.

COLUMN 3:

Line 29, "a (CD1" should read --a CCD1--.

COLUMN 5:

Line 57, "frames." should read --frame.--.

COLUMN 6:

Line 13, "facilitate" should read --facilitates--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,038,724 B2</u>

No. of add'l. copies @ 30¢ per page

OCT - 3 2008



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 9, "memory 13C" should read --memory 130--;

Line 10, "such." should read --such--;

Line 53, "106 in" should read -- 106 is in--; and

Line 56, "time" should read --time:--.

COLUMN 10:

Line 1, "components" should read --component--.

COLUMN 11:

Line 62, "second resolution" should read --second-resolution--.

COLUMN 12:

Line 4, "first-and" should read --first- and--;

Line 15, "a" should read --an--;

Line 37, "second resolution" should read --second-resolution--; and

Line 52, "first-and" should read --first- and--.

COLUMN 13:

Line 10, "wits" should read --puts--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,038,724 B2</u>

met - 3 2000

No. of add'l. copies @ 30¢ per page



Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 7,038,724 B2

DATED

May 2, 2006

INVENTOR(S) :

MAKOTO SATOH ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 6, "second" should read --second---.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

- 3 **700**

PATENT NO. <u>US 7,038,724 B2</u>

No. of add'l. copies @ 30¢ per page

